


Comments:

1. Check assemblability.
2. Perform Assembly as shown on drawings.
3. Make a trial motions of individual mechanisms and moving parts to verify the correctness of installation.
4. Protect against damage and corrosion until main installation.

2	6	Basket		STB 02.00.00		0	6.9				
1	1	Frame		STB 01.00.00		0	14.4				
Item	Qty.	Name of part		Drawing number, standard	Rev.	Material	Weight 1pcs. kg	Comments			
		Weight 1 set 55,9 kg		Drawing name Subject Title							
Engin.	2017-07-28				SSB 00.00.00						
Draw.	2017-07-28										
Check.	2017-07-28				Revision						
Ver.	2017-07-28				0						
Appr.	2017-07-28										
<div>papacad</div> <div>3D & 2D Professional CAD Designs for Download</div>				<div>www.papacad.com</div>		<div></div>		Scale		Format	
								1 : 5		A2	
								Sheet			
								1 / 1			